







## Instructions



Use a pen whose ink has dried out, or a tracer, to trace lines first.



Separate all parts along the lines. Mark their identity on the back to avoid confusion.



Fold and glue W01.





Glue W01, W02, W03 and W04 according to the assembly instruction, Letter "W" is now done.